Form Numb. 40-005414

## LIBBY ASBESTOS PROJECT Property Closeout Checklist (PCC) Revision 3

Form Date: 8-3-09

ield Logbook No.: 101121 Page No.'s: 19,15,4
ddress: Libby Creek City: Libby
occupant: NA
wner: State of montana
versight Personnel: K. Beauton, S. Mc Nally
emoval Contractor: FR
estoration Contractor: EK
ssociated BD Numbers:
CC Check Completed by (100% of forms): Miching lafe: 10/21/09

Data Item	Value		Comments		
Type of removal activity circle all that apply	VCI removal Interior cleaning Exterior removal Building materials Other: Rupsep		Circle all that apply:  Quick Response   Partial Removal		
	Start	Finish			
Interior setup date(s)	NA	NA	NA implies interior work not needed		
Interior removal date(s)	NA	N (t	NA implies interior work not needed		
Interior restoration date(s)	NA	S. Par. Con	NA implies interior work not needed		
Exterior setup date(s)	8-3-09	8-4-09	NA implies exterior work not needed		
Exterior removal date(s)	8-4-09	8-25-09	NA implies exterior work not needed		
Exterior restoration date(s)	8-17-09	0 13 65	NA implies exterior work not needed		
Total days at property [include weekends]	.39	32 Liely (09)			
Contaminated material removed circle all that apply	Soil  VCI  Other insulation  Household items  Rubbish/Debris  Other Rugs				

Data Item	Value	Comments		
Cubic yards (Yd3) of contam	inated material removed	:		
Soil	<u>499</u> Yd <sup>3</sup>			
VCI	Yd³			
Other insulation	Yd³	Type of insulation removed:		
Household items	Description:			
Rubbish/Debris	95 Truckloads	Description: Riprap		
Any contaminated material remaining after removal is complete? [responses must be consistent within the shaded sections]	No - circle if next two it Sott> - circle if Contamina VCI - circle if VCI remain	ted soll remaining is circled below		
[responses must be consistent within the shaded sections]  Contaminated soil remaining	Location description:  Accors A2 A35  Libby Amobibol	Al, mortolelog Al, morty mad <17 at 12-14" B65		
NA [When revising this section also revise corresponding item in shaded section above]	Aicas DH. Al, Bl.	A2, A3, B2 had visible		
[responses must be consistent within the shaded sections]  VCI remaining  (When revising this section also revise corresponding item in	Location description: [in information]	clude RAWP Addendum background		
shaded section above]				

Data Item	Value	Comments		
Cubic yards (Yd³) of material replaced:				
Insulation	Yd <sup>3</sup>	Type:		
	NA_			
Residential fill	244 Yd3			
	NA			
Topsoil	Yd³			
	(NA)			
Other material (i.e., gravel)	( <u>a) 237,(<b>b</b>)(137)</u> Yd <sup>3</sup> (C) <i>1000</i> NA	Type: (9) 34" Arnus Crushed Kock (6) 24 MANUS CRUSHED KOCK (C) RIPTAP		
HEPA vacuum given to	Date:	Reason:		
resident?	Not given			
Items damaged during construction	<ul> <li>See removal and restoration checklist</li> </ul>			
	None			
ADDITIONAL INFORMATIO	, <u>)N</u>			
One Amendment	Two mods	·		
·				
	<del> </del>	· · · · · · · · · · · · · · · · · · ·		
· · · · · · · · · · · · · · · · · · ·		·		
<del></del>				
	<del></del>			
		<del></del>		
<del></del>				

a	M
	AN

CLIENT	JOB NO	A	COMPUTED BY	
PROJECT	 DATE CHECKED		DATE	
DETAIL	 CHECKED BY	<u> </u>	PAGE NO.	

2R- 07083

> AREA C, B3

ND

LIBBY CREEK MONTANA

SP- 141276

NO VISIBLE

2R- 07084

> AREA B2

ND Visible (1 low)

SP- 141277

2R- 07087

> AREA BI 12-14" ND Visible observed (1 Low)

SP- 141278

2R- 07126

SP- 141293

AREAD 12-14" ND resampled as Area Da

2R- 07133

> AREA A2

Z1º/6.

SP- 141300

(7 low)

2R- 07134

> AREA A3

∠10/0 Unsible observed (6/00)

SP- 141301

Page 4 of 6

2R- 07509

AREA A1 > 12-14" BGS

LIBBY CREEK 41% ANATINOM

SP- 141305

2 low visible

2R-07510

AREA A4 1214" BGS

196 ND no visible

SP- 141306

2R-07273

SP- 140813

Area A5,D2 48"-74"

ND 1 Low visible

